CLEANING AND MAINTENANCE INSTRUCTIONS FOR GLAZING

Always protect product from contaminating substances.

Do not allow foreign substances to remain on surface of glass.

In general the glass surfaces should be cleaned on a regular basis. The level of pollution or contaminants in the surrounding area determines the frequency.

Glass should be cleaned using soft clean cloths, chamois leathers, sponges, or soft paper.

Use clean warm water with a mild liquid detergent. Proprietary glass cleaners may also be used.

Do not use detergents that contain either alkaline, acids or fluoride. Abrasive cleaning methods i.e. scouring pads, steel wool, and razor blades should only be used for spot cleaning, as damage to the surface may result.



Note: Never use abrasives on the filmed side of WireShield, KeraShield or other glazings with an applied film.

It is not recommended to clean the whole surface of the glass with a blade or squeegee.

TIPS ON VISUAL QUALITY OF FILMED GLASS:

The glass with applied film shall be viewed at right angles to the glass from the room side, at a distance of not less than 6 feet (2 meters). Viewing shall be carried out in natural daylight, not in direct sunlight, and shall assess the normal vision area with the exceptions of a 2 inch (50mm) wide band around the perimeter of the unit.

The installation shall be deemed acceptable if any of the following are unobtrusive (effects during visual cure should be disregarded): Dirt Particles, Hair and Fibers, Adhesive Gels, Fingerprints, Air Bubbles, Water Haze, Scores and Scratches, Film Distortion, Creases, Edge Life, Nicks and Tears. -- As adopted by IWFA May 15, 1999





Cleaning and Maintenance Instructions



Distributed by www.AmeraProducts.com Phone: (800) 608-6568 Fax: (409) 840-5545 info@ameraproducts.com